

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

**FI810**  
**West**  
**> 1**  
**1.123 mi.**  
**5929 ft.**

**MANHOLE 58156**  
**NEPTUNE AV / WEST 33RD ST**  
**BROOKLYN, NY**

**NY Spills** **S103829318**  
**N/A**

**Site 3 of 5 in cluster FI**

**Relative:**  
**Higher**

**Actual:**  
**0 ft.**

**SPILLS:**

Name: MANHOLE 58156  
Address: NEPTUNE AV / WEST 33RD ST  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9815192 / 2002-06-06  
Facility ID: 9815192  
Facility Type: ER  
DER Facility ID: 241606  
Site ID: 298642  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 1999-03-23  
Investigator: CAENGELH  
Referred To: Not reported  
Reported to Dept: 1999-03-23  
CID: 312  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1999-03-23  
Spill Record Last Update: 2002-06-06  
Spiller Name: Not reported  
Spiller Company: CON EDISON  
Spiller Address: 4 IRVING PLACE  
Spiller Company: 999  
Contact Name: Not reported  
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
ENGELHARDT Con Ed e2mis #123805: H.LEARNER #33490 SENIOR FIELD  
OPERATOR REPORTS AFTER PUMPING WATER OUT OF MH 58156 FOUND APPROX 1/2  
GALLON OF SLUDGE MIXED WITH AN UNKNOWN OIL ON FLOOR OF MH. NO SEWERS  
OR WATERWAYS AFFECTED, SAMPLE TAKEN & STOP TAG # 06954 PLACED.  
CLEANUP PENDING TEST RESULTS. #12255 VDC.NOTE CREW ON LOCATION  
SHOOTING FAULT ON FEEDER. 24-MAR-1999 0053HRS LAB RESULTS RETURNED 1  
PPM LAB SEQUENCE # IS 99-02077 3-29-99 20:00HRS F. DELLATORRE  
REPORTS, CLEANUP COMPLETED WITH SLIX & TAG # 06954 REMOVED. "  
"1/2 GAL OF OIL/SLUDGE MIXTURE CONTAINED IN MANHOLE - CASE #123805"

**Remarks:**

**All Materials:**

Site ID: 298642  
Operable Unit ID: 1073220  
Operable Unit: 01  
Material ID: 308309  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Quantity: 1.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Site ID: 298642  
Operable Unit ID: 1073220  
Operable Unit: 01  
Material ID: 308310  
Material Code: 0058A  
Material Name: sludge

Case No.: Not reported  
Material FA: Other  
Quantity: 1.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported